

Compatibility of Nav N Go iGO 8 with PDA-devices



Legend: ✓ : compatible, ⓘ : compatible, but see notes, ✗ : not compatible, ? : not tested

Tested PDA			Tested with			
Manu- facturer	Type	Tested with operating system	Nav N Go iGO 8 R1 (v8.0.0.31442)	Nav N Go iGO 8 R1 update (v8.0.0.49545)	Nav N Go iGO 8 HTC Touch Diamond edition	Nav N Go iGO 8 Samsung Omnia (i900) edition
Airis	T482	Windows Mobile 6 Professional	ⓘ	✓	?	?
Airis	T620	Microsoft Windows Mobile 5.0	✓	✓	?	?
Alltel	Palm Treo 700wx	Windows Mobile 5.0 for Pocket PC Phone Edition	✗	?	?	?
ASUS	MyPal A639	Microsoft Windows Mobile 6 Classic	ⓘ	ⓘ	?	?
ASUS	MyPal A686	Microsoft Windows Mobile 6 Classic	ⓘ	✓	?	?
ASUS	MyPal A696	Microsoft Windows Mobile 6 Classic	ⓘ	✓	?	?
ASUS	P320	Windows Mobile 6.1 Professional	ⓘ	✓	?	?
ASUS	P526	Windows Mobile 6 Professional	✗	✗	?	?
ASUS	P527	Windows Mobile 6 Professional	✗	✗	?	?
ASUS	P535	M W Mobile 5.0 with the M and S F P	ⓘ	✓	?	?
ASUS	P750	Windows Mobile 6 Professional	ⓘ	ⓘ	?	?
AT&T	Palm Treo 750	M W Mobile 5.0 for Pocket PC Phone Edition	✗	?	?	?
Dell	Axim X51v	Microsoft Windows Mobile 6 Classic	ⓘ	✓	?	?
Eten	Glofiish M700	M W Mobile 5.0 with the M and S F P	ⓘ	✓	?	?
Eten	Glofiish M750	Windows Mobile 6 Professional	ⓘ	✓	?	?
Eten	Glofiish M800	Windows Mobile 6 Professional	✗	✗	?	?
Eten	Glofiish M810	Windows Mobile 6 Professional	ⓘ	✓	?	?
Eten	Glofiish V900/X900	Windows Mobile 6.1 Professional	✗	✗	?	?
Eten	Glofiish X500	M W Mobile 5.0 with the M and S F P	ⓘ	✓	?	?
Eten	Glofiish X500+	Windows Mobile 6	✗	✗	?	?
Eten	Glofiish X600	Windows Mobile 6 Professional	ⓘ	ⓘ	?	?
Eten	Glofiish X610	Windows Mobile 6 Professional	ⓘ	ⓘ	?	?
Eten	Glofiish X650	Windows Mobile 6 Professional	✗	✗	?	?
Eten	Glofiish X800	Windows Mobile 6 Professional	✗	✗	?	?

Compatibility of Nav N Go iGO 8 with PDA-devices



Legend: ✓ : compatible, ⓘ : compatible, but see notes, ✗ : not compatible, ? : not tested

Tested PDA			Tested with			
Manu- facturer	Type	Tested with operating system	Nav N Go iGO 8 R1 (v8.0.0.31442)	Nav N Go iGO 8 R1 update (v8.0.0.49545)	Nav N Go iGO 8 HTC Touch Diamond edition	Nav N Go iGO 8 Samsung Omnia (i900) edition
Fujitsu-Siemens	Pocket LOOX 720	M Windows Mobile 2003 Second Edition	✓	✓	?	?
Fujitsu-Siemens	Pocket LOOX N500	Microsoft Windows Mobile version 5.0	ⓘ	✓	?	?
Fujitsu-Siemens	Pocket LOOX N520	M W M 5.0 for Pocket PC Premium Edition	ⓘ	✓	?	?
Fujitsu-Siemens	Pocket LOOX N560	Microsoft Windows Mobile version 5.0	ⓘ	ⓘ	?	?
Fujitsu-Siemens	Pocket LOOX T830	Microsoft Windows Mobile version 5.0	✗	ⓘ	?	?
Gigabyte	g-Smart i	M Windows Mobile 5.0 with the M and S F P	ⓘ	✓	?	?
HP	iPAQ 610/614 Business Navigator	Windows Mobile 6 Professional	ⓘ	ⓘ	?	?
HP	iPAQ 910 Business Navigator	Windows Mobile 6.1 Professional	✗	✗	?	?
HP	iPAQ h1915	Microsoft Windows Mobile 2002	✗	✗	?	?
HP	iPAQ h2210	Microsoft Windows Mobile 2003	✗	✓	?	?
HP	iPAQ h4150	Microsoft Windows Mobile 2003	✗	✓	?	?
HP	iPAQ hw6515	M W M 2003 for PPC Phone E Second Edition	✗	?	?	?
HP	iPAQ hx2110	Microsoft Windows Mobile Version 5.0	ⓘ	ⓘ	?	?
HP	iPAQ rw6815 Personal Messenger	Microsoft Windows Mobile Version 5.0	✓	✓	?	?
HP	iPAQ rx5940 Travel Companion	Microsoft Windows Mobile 5.0	ⓘ	✓	?	?
HTC	Artemis (P3300)	M Windows Mobile 5.0 with the M and S F P	ⓘ	ⓘ	?	?
HTC	Athena 100 (X7500)	M Windows Mobile 5.0 with the M and S F P	ⓘ	✓	?	?
HTC	Athena 400 (X7510)	Windows Mobile 6.1 Professional	✗	ⓘ	?	?
HTC	Excalibur (S620)	M Windows Mobile 5.0 with the M and S F P	✗	✗	?	?
HTC	Herald (P4350)	Windows Mobile 6 Professional	?	ⓘ	?	?
HTC	Pharos (P3470)	Windows Mobile 6 Professional	ⓘ	✓	?	?
HTC	Sedna (P6500)	Windows Mobile 6 Professional	?	ⓘ	?	?
HTC	Touch (P3450)	Windows Mobile 6 Professional	✗	✗	?	?
HTC	Touch Pro (T7272, Raphael)	Windows Mobile 6.1 Professional	✗	ⓘ	?	?

Compatibility of Nav N Go iGO 8 with PDA-devices



Legend: ✓ : compatible, ⓘ : compatible, but see notes, ✗ : not compatible, ? : not tested

Tested PDA			Tested with			
Manu- facturer	Type	Tested with operating system	Nav N Go iGO 8 R1 (v8.0.0.31442)	Nav N Go iGO 8 R1 update (v8.0.0.49545)	Nav N Go iGO 8 HTC Touch Diamond edition	Nav N Go iGO 8 Samsung Omnia (i900) edition
HTC	Touch Cruise (P3650, Polaris)	Windows Mobile 6 Professional	✓	✓	?	?
HTC	Touch Dual (20 key) 5520	Windows Mobile 6 Professional	?	✓	?	?
HTC	Touch Diamond (P3700)	Windows Mobile 6.1 Professional	✗	✗	✓	?
HTC	TyTn (P4500, Hermes 200)	M Windows Mobile 5.0 with the M and S F P	ⓘ	✓	?	?
HTC	TyTN II (Kaiser)	Windows Mobile 6.1 Professional	✗	✓	?	?
MITAC Mio	168	Windows Mobile 2003 Second Edition	✓	✓	?	?
MITAC Mio	169	M Windows Mobile 2003 Second Edition	✓	✓	?	?
MITAC Mio	180	Windows Mobile 2003 Second Edition	✓	✓	?	?
MITAC Mio	A501	M W M 6 Pro AND WM 5.0 with the M and S F P	✓	✓	?	?
MITAC Mio	A701	M W Mobile 5.0 for Pocket PC Phone Edition	✓	✓	?	?
MITAC Mio	A702	Windows Mobile 6 Professional	✓	✓	?	?
MITAC Mio	P350	M W M 5.0 for Pocket PC Premium Edition	✓	✓	?	?
MITAC Mio	P360	Microsoft Windows Mobile 6 Classic	✓	✓	?	?
MITAC Mio	P560	Microsoft Windows Mobile 6 Classic	✓	✓	?	?
MyGuide	3500	M W Mobile 2003 Zweite Ausgabe	ⓘ	ⓘ	?	?
MyGuide	7500XL	Windows Mobile 5.0 for Pocket PC	✓	✓	?	?
Palm	Treo 700w	Microsoft Windows Mobile 5.0	✗	✗	?	?
Palm	Treo 750	Microsoft Windows Mobile 5.0	✗	✓	?	?
Samsung	SGH-i780	Windows Mobile 6 Professional	✗	✓	?	?
Samsung	SGH-i900	Windows Mobile 6.1 Professional	✗	ⓘ	?	✓
Toshiba	e800 WIFI	M W Mobile 2003 Second Edition	✗	✗	?	?
Toshiba	Portege G810	Windows Mobile 6.1 Professional	ⓘ	✓	?	?
Toshiba	Portege G910	Windows Mobile 6 Professional	✗	ⓘ	?	?
Yakumo	deltaX 5 BT	M W M 5.0 for Pocket PC Professional Edition	ⓘ	✓	?	?

Compatibility of Nav N Go iGO 8 with PDA-devices



Legend: ✓ : compatible, Ⓛ : compatible, but see r

Tested PDA			Compatibility notes for Nav N Go iGO 8 R1 (v8.0.0.31442)
Manu- facturer	Type	Tested with operating system	
Airis	T482	Windows Mobile 6 Professional	Backlight problem, GPS connection should be configured manually.
Airis	T620	Microsoft Windows Mobile 5.0	
Alltel	Palm Treo 700wx	Windows Mobile 5.0 for Pocket PC Phone Edition	
ASUS	MyPal A639	Microsoft Windows Mobile 6 Classic	Backlight problem
ASUS	MyPal A686	Microsoft Windows Mobile 6 Classic	Manual configuration is required before first run, screen orientation problem, backlight problem
ASUS	MyPal A696	Microsoft Windows Mobile 6 Classic	Manual configuration is required before first run, screen orientation problem, backlight problem
ASUS	P320	Windows Mobile 6.1 Professional	Backlight problem, GPS connection should be configured manually.
ASUS	P526	Windows Mobile 6 Professional	
ASUS	P527	Windows Mobile 6 Professional	
ASUS	P535	M W Mobile 5.0 with the M and S F P	Backlight problem
ASUS	P750	Windows Mobile 6 Professional	Backlight problem, GPS connection should be configured manually.
AT&T	Palm Treo 750	M W Mobile 5.0 for Pocket PC Phone Edition	
Dell	Axim X51v	Microsoft Windows Mobile 6 Classic	Backlight problem
Eten	Glofiish M700	M W Mobile 5.0 with the M and S F P	Backlight problem, GPS connection should be configured manually.
Eten	Glofiish M750	Windows Mobile 6 Professional	Backlight problem, GPS connection should be configured manually.
Eten	Glofiish M800	Windows Mobile 6 Professional	
Eten	Glofiish M810	Windows Mobile 6 Professional	Backlight problem, GPS connection should be configured manually.
Eten	Glofiish V900/X900	Windows Mobile 6.1 Professional	
Eten	Glofiish X500	M W Mobile 5.0 with the M and S F P	Backlight problem, GPS connection should be configured manually.
Eten	Glofiish X500+	Windows Mobile 6	
Eten	Glofiish X600	Windows Mobile 6 Professional	Backlight problem, GPS connection should be configured manually., Sound problem(max volume)
Eten	Glofiish X610	Windows Mobile 6 Professional	Backlight problem, GPS connection should be configured manually.
Eten	Glofiish X650	Windows Mobile 6 Professional	
Eten	Glofiish X800	Windows Mobile 6 Professional	

Compatibility of Nav N Go iGO 8 with PDA-devices



Legend: ✓ : compatible, Ⓢ : compatible, but see r

Tested PDA			Compatibility notes for Nav N Go iGO 8 R1 (v8.0.0.31442)
Manu- facturer	Type	Tested with operating system	
Fujitsu-Siemens	Pocket LOOX 720	M Windows Mobile 2003 Second Edition	
Fujitsu-Siemens	Pocket LOOX N500	Microsoft Windows Mobile version 5.0	Backlight problem
Fujitsu-Siemens	Pocket LOOX N520	M W M 5.0 for Pocket PC Premium Edition	Backlight problem
Fujitsu-Siemens	Pocket LOOX N560	Microsoft Windows Mobile version 5.0	Out of memory error might appear. Backlight problem
Fujitsu-Siemens	Pocket LOOX T830	Microsoft Windows Mobile version 5.0	
Gigabyte	g-Smart i	M Windows Mobile 5.0 with the M and S F P	Backlight problem
HP	iPAQ 610/614 Business Navigator	Windows Mobile 6 Professional	GPS connection should be configured manually., Backlight problem
HP	iPAQ 910 Business Navigator	Windows Mobile 6.1 Professional	
HP	iPAQ h1915	Microsoft Windows Mobile 2002	
HP	iPAQ h2210	Microsoft Windows Mobile 2003	
HP	iPAQ h4150	Microsoft Windows Mobile 2003	
HP	iPAQ hw6515	M W M 2003 for PPC Phone E Second Edition	
HP	iPAQ hx2110	Microsoft Windows Mobile Version 5.0	Out of memory error might appear.
HP	iPAQ rw6815 Personal Messenger	Microsoft Windows Mobile Version 5.0	
HP	iPAQ rx5940 Travel Companion	Microsoft Windows Mobile 5.0	GPS connection should be configured manually.
HTC	Artemis (P3300)	M Windows Mobile 5.0 with the M and S F P	Backlight problem
HTC	Athena 100 (X7500)	M Windows Mobile 5.0 with the M and S F P	GPS connection should be configured manually.
HTC	Athena 400 (X7510)	Windows Mobile 6.1 Professional	
HTC	Excalibur (S620)	M Windows Mobile 5.0 with the M and S F P	
HTC	Herald (P4350)	Windows Mobile 6 Professional	
HTC	Pharos (P3470)	Windows Mobile 6 Professional	Manual configuration is required before first run, backlight problem
HTC	Sedna (P6500)	Windows Mobile 6 Professional	
HTC	Touch (P3450)	Windows Mobile 6 Professional	
HTC	Touch Pro (T7272, Raphael)	Windows Mobile 6.1 Professional	

Compatibility of Nav N Go iGO 8 with PDA-devices



Legend: ✓ : compatible, Ⓛ : compatible, but see r

Tested PDA			Compatibility notes for Nav N Go iGO 8 R1 (v8.0.0.31442)
Manufacturer	Type	Tested with operating system	
HTC	Touch Cruise (P3650, Polaris)	Windows Mobile 6 Professional	
HTC	Touch Dual (20 key) 5520	Windows Mobile 6 Professional	
HTC	Touch Diamond (P3700)	Windows Mobile 6.1 Professional	
HTC	TyTn (P4500, Hermes 200)	M Windows Mobile 5.0 with the M and S F P	Backlight problem
HTC	TyTN II (Kaiser)	Windows Mobile 6.1 Professional	
MITAC Mio	168	Windows Mobile 2003 Second Edition	
MITAC Mio	169	M Windows Mobile 2003 Second Edition	
MITAC Mio	180	Windows Mobile 2003 Second Edition	
MITAC Mio	A501	M W M 6 Pro AND WM 5.0 with the M and S F P	
MITAC Mio	A701	M W Mobile 5.0 for Pocket PC Phone Edition	
MITAC Mio	A702	Windows Mobile 6 Professional	
MITAC Mio	P350	M W M 5.0 for Pocket PC Premium Edition	
MITAC Mio	P360	Microsoft Windows Mobile 6 Classic	
MITAC Mio	P560	Microsoft Windows Mobile 6 Classic	
MyGuide	3500	M W Mobile 2003 Zweite Ausgabe	GPS connection should be configured manually.
MyGuide	7500XL	Windows Mobile 5.0 for Pocket PC	
Palm	Treo 700w	Microsoft Windows Mobile 5.0	
Palm	Treo 750	Microsoft Windows Mobile 5.0	
Samsung	SGH-i780	Windows Mobile 6 Professional	
Samsung	SGH-i900	Windows Mobile 6.1 Professional	
Toshiba	e800 WIFI	M W Mobile 2003 Second Edition	
Toshiba	Portege G810	Windows Mobile 6.1 Professional	Manual configuration is required before first run, backlight problem, GPS connection should be configured manually.
Toshiba	Portege G910	Windows Mobile 6 Professional	
Yakumo	deltaX 5 BT	M W M 5.0 for Pocket PC Professional Edition	Backlight problem, GPS connection should be configured manually.

Compatibility of Nav N Go iGO 8 with PDA-devices



Legend: ✓ : compatible, Ⓛ : compatible, but see r

Tested PDA			Compatibility notes for Nav N Go iGO 8 R1 update (v8.0.0.49545)
Manu- facturer	Type	Tested with operating system	
Airis	T482	Windows Mobile 6 Professional	
Airis	T620	Microsoft Windows Mobile 5.0	
Alltel	Palm Treo 700wx	Windows Mobile 5.0 for Pocket PC Phone Edition	
ASUS	MyPal A639	Microsoft Windows Mobile 6 Classic	GPS connection should be configured manually.
ASUS	MyPal A686	Microsoft Windows Mobile 6 Classic	
ASUS	MyPal A696	Microsoft Windows Mobile 6 Classic	
ASUS	P320	Windows Mobile 6.1 Professional	
ASUS	P526	Windows Mobile 6 Professional	
ASUS	P527	Windows Mobile 6 Professional	
ASUS	P535	M W Mobile 5.0 with the M and S F P	
ASUS	P750	Windows Mobile 6 Professional	Out of memory error might appear, GPS connection should be configured manually.
AT&T	Palm Treo 750	M W Mobile 5.0 for Pocket PC Phone Edition	
Dell	Axim X51v	Microsoft Windows Mobile 6 Classic	
Eten	Glofiish M700	M W Mobile 5.0 with the M and S F P	
Eten	Glofiish M750	Windows Mobile 6 Professional	
Eten	Glofiish M800	Windows Mobile 6 Professional	
Eten	Glofiish M810	Windows Mobile 6 Professional	
Eten	Glofiish V900/X900	Windows Mobile 6.1 Professional	
Eten	Glofiish X500	M W Mobile 5.0 with the M and S F P	
Eten	Glofiish X500+	Windows Mobile 6	
Eten	Glofiish X600	Windows Mobile 6 Professional	Sound problem (max volume)
Eten	Glofiish X610	Windows Mobile 6 Professional	GPS connection should be configured manually.
Eten	Glofiish X650	Windows Mobile 6 Professional	
Eten	Glofiish X800	Windows Mobile 6 Professional	

Compatibility of Nav N Go iGO 8 with PDA-devices



Legend: ✓ : compatible, Ⓢ : compatible, but see r

Tested PDA			Compatibility notes for Nav N Go iGO 8 R1 update (v8.0.0.49545)
Manu- facturer	Type	Tested with operating system	
Fujitsu-Siemens	Pocket LOOX 720	M Windows Mobile 2003 Second Edition	
Fujitsu-Siemens	Pocket LOOX N500	Microsoft Windows Mobile version 5.0	
Fujitsu-Siemens	Pocket LOOX N520	M W M 5.0 for Pocket PC Premium Edition	
Fujitsu-Siemens	Pocket LOOX N560	Microsoft Windows Mobile version 5.0	Out of memory error might appear.
Fujitsu-Siemens	Pocket LOOX T830	Microsoft Windows Mobile version 5.0	GPS connection should be configured manually, Backlight problem
Gigabyte	g-Smart i	M Windows Mobile 5.0 with the M and S F P	
HP	iPAQ 610/614 Business Navigator	Windows Mobile 6 Professional	Backlight problem
HP	iPAQ 910 Business Navigator	Windows Mobile 6.1 Professional	
HP	iPAQ h1915	Microsoft Windows Mobile 2002	
HP	iPAQ h2210	Microsoft Windows Mobile 2003	
HP	iPAQ h4150	Microsoft Windows Mobile 2003	
HP	iPAQ hw6515	M W M 2003 for PPC Phone E Second Edition	
HP	iPAQ hx2110	Microsoft Windows Mobile Version 5.0	Out of memory error might appear.
HP	iPAQ rw6815 Personal Messenger	Microsoft Windows Mobile Version 5.0	
HP	iPAQ rx5940 Travel Companion	Microsoft Windows Mobile 5.0	
HTC	Artemis (P3300)	M Windows Mobile 5.0 with the M and S F P	Navigation can be very slow. Device is not supported due to performance issues.
HTC	Athena 100 (X7500)	M Windows Mobile 5.0 with the M and S F P	
HTC	Athena 400 (X7510)	Windows Mobile 6.1 Professional	GPS connection should be configured manually, Backlight problem
HTC	Excalibur (S620)	M Windows Mobile 5.0 with the M and S F P	
HTC	Herald (P4350)	Windows Mobile 6 Professional	Out of memory error might appear.
HTC	Pharos (P3470)	Windows Mobile 6 Professional	
HTC	Sedna (P6500)	Windows Mobile 6 Professional	GPS connection should be configured manually, Backlight problem
HTC	Touch (P3450)	Windows Mobile 6 Professional	
HTC	Touch Pro (T7272, Raphael)	Windows Mobile 6.1 Professional	Manual configuration is required before first run, GPS connection should be configured manually, backlight problem

Compatibility of Nav N Go iGO 8 with PDA-devices



Legend: ✓ : compatible, Ⓛ : compatible, but see r

Tested PDA			Compatibility notes for Nav N Go iGO 8 R1 update (v8.0.0.49545)
Manu- facturer	Type	Tested with operating system	
HTC	Touch Cruise (P3650, Polaris)	Windows Mobile 6 Professional	
HTC	Touch Dual (20 key) 5520	Windows Mobile 6 Professional	
HTC	Touch Diamond (P3700)	Windows Mobile 6.1 Professional	
HTC	TyTn (P4500, Hermes 200)	M Windows Mobile 5.0 with the M and S F P	
HTC	TyTN II (Kaiser)	Windows Mobile 6.1 Professional	
MITAC Mio	168	Windows Mobile 2003 Second Edition	
MITAC Mio	169	M Windows Mobile 2003 Second Edition	
MITAC Mio	180	Windows Mobile 2003 Second Edition	
MITAC Mio	A501	M W M 6 Pro AND WM 5.0 with the M and S F P	
MITAC Mio	A701	M W Mobile 5.0 for Pocket PC Phone Edition	
MITAC Mio	A702	Windows Mobile 6 Professional	
MITAC Mio	P350	M W M 5.0 for Pocket PC Premium Edition	
MITAC Mio	P360	Microsoft Windows Mobile 6 Classic	
MITAC Mio	P560	Microsoft Windows Mobile 6 Classic	
MyGuide	3500	M W Mobile 2003 Zweite Ausgabe	GPS connection should be configured manually.
MyGuide	7500XL	Windows Mobile 5.0 for Pocket PC	
Palm	Treo 700w	Microsoft Windows Mobile 5.0	
Palm	Treo 750	Microsoft Windows Mobile 5.0	
Samsung	SGH-i780	Windows Mobile 6 Professional	
Samsung	SGH-i900	Windows Mobile 6.1 Professional	GPS connection should be configured manually, Screen orientation problem, No autorun of the software
Toshiba	e800 WIFI	M W Mobile 2003 Second Edition	
Toshiba	Portege G810	Windows Mobile 6.1 Professional	
Toshiba	Portege G910	Windows Mobile 6 Professional	Screen orientation problem.
Yakumo	deltaX 5 BT	M W M 5.0 for Pocket PC Professional Edition	